STATE FORM

Division of Health Care Facilities

តោ ០០ឧ/ ០០ឧ

PRINTED: 06/16/2011 FORM APPROVED

		IDENTIFICATION NUMBER				COMPLETED 06/13/2011	
	ROVIDER OR SUPPLIER	129	EET ADDRESS, CITY, ST 9 HILLCREST DRIVE RDSTOWN, TN 385	E ***	00/1	0/2011	
(X4) 1D PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			PROVIDER'S PLAN OF COR (EACH CORRECTIVE ACTION CROSS-REFERENCED TO THE A DEFICIENCY)	VE ACTION SHOULD BE ED TO THE APPROPRIATE		
	arranged and main the resident.  This Rule is not m Based on observat facility failed to ma ensure the safety of the findings included on 6/13/11 at 3:05 room131 bathroom floor was damaged finding was correct. This finding was ac Administrator and second the resident of	ome must be constructed, itained to ensure the safe set as evidenced by: tions, it was determined the intain the nursing home to of the residents as require	ty of line of	N 831 Corrective Actions for resaffected:  Floor was repaired by Maint Supervisor as stated on the facility had already been in preplacing the restroom floor this hall and this was the final Identification of residents to be affected: On 6/14/11 the Maintenance examined all other flooring for repair with no other findings  K 038 continued Measures to prevent reoccurrent Maintenance Supervisor monthly safety walkthrough examination for restroom florepair. Repairs will be facility facility Maintenance Supervisor contractor as need arises.  Monitoring of Corrective As a means of Quality Assume Maintenance Supervisor will to the monthly safety commit	enance 2567. The process of coverings for al room.  with potential e Supervisor or any need of discovered.  currence: r conducts a that will include ors for need of ated by the sor or by hired  action: cance the report findings	6 13	

NMVW21